UTTERMOST LIGHTING
ASSEMBLY INSTRUCTIONS

ITEM # : 22209

IMPORTANT : TURN OFF THE POWER AT THE MAIN FUSE OR CIRCUIT BREAKER BOX BEFORE STARTING INSTALLATION

Carefully unpack and identify all parts before assembly.

1.Be sure the power to the installation point is off.
2.Pull the power supply wires out from the outlet box, and mount the cross bar to the outlet box, using mounting screws.
3.Attach the power supply wires to the fixture lead wires by connecting black to black, and white to white. Attach the power supply ground wire from the outlet box and the fixture ground wire from the fixture to the green ground screw on the mounting bracket or connect both wires together using the correct size of wire connectors.
4.Install the nipple onto the cross bar with hexnut A & washer A and secure until snug.
5.Install the canopy over the nipple with ball finial.
6.Screw center stem into hex coupling.
7.Install glass shade onto fitters by fastening hexnut B.
8.Install cap B onto center stem by fastening with finial.
9.Install bulbs(no included). See relamping label located at socket area for type and maximum allowed wattage.