

# UTTERMOST LIGHTING ASSEMBLY INSTRUCTIONS

ITEM # : 21045

**IMPORTANT : TURN OFF THE POWER AT THE MAIN FUSE  
OR CIRCUIT BREAKER BOX  
BEFORE STARTING INSTALLATION**

**Carefully unpack and identify all parts before assembly.**

1. Install glass shade with washer A onto threaded sockets.
2. Install stabilizer onto fitters by fastening counter rings onto threaded sockets.
3. Screw center stem into hex coupling.
4. Install glass ball with washer B onto fitters by fastening hexnut.
5. Install cap onto center stud by fastening with finial.
6. Install bulbs (no included). See relamping label located at socket area for type and maximum allowed wattage.
7. Locate the lower assembly upward and match the hooks on to the up and ends of support arms. Locate the ends of support arms on to the hooks inside arms.

