UTTERMOST ASSEMBLY INSTRUCTIONS

Item :22909


Parts/Hardware list

А	Legs	4 PCS	В	Top Frame	1 PC
С	Stretcher	1 PC	D	Felt Pad	4 PCS
Е	Top Tempered Glass	1 PC	F	Screws	12 PCS

1. Take the parts carefully out of the carton, and place them on a flat and soft surface, making sure that the parts will not be damaged.


2.Assemble the Legs(A) on Top Frame(B) together using 8 Screws.

Please match color dot near screw holes.






- 3.Assemble the Stretcher(C) on the Legs(A) together using 4 Screws. Please match color dot near screw holes.
- 4.Stick the Felt Pads(D) on the bottom of the Legs(A).



5.Turn over the table top, place the Top Tempered Glass (E) on Top Frame(B).



(3) To clean,wipe with soft dry cloth.



1.To avoid table tipping over, please read all instructions carefully and completely before beginning use.

2. Save all packing materials until table is secured on wall to avoid accidentally discarding any parts or hardware.


Part and hardware list

A	A B		Tool needed but not supplied	
Metal Bracket	2" Screw	Plastic	Pencil-one pc, tape measure-one pc, screw driver	
WIEtal Diacket		Strap	pc,	
1PC	1PC	1PC		

Anti- tipping Instructions

1. Use a pencil to mark desired location for screw on wall. The location must be 1 inch lower than the height of sawtooth which is located at the center-back of the table frame. Locate the metal bracket (A) on the wall and attach it through the smaller hole to the wall

2.Place table near wall. Then lace the end of plastic strap (C) through the large hole of the metal bracket pre-mounted on the wall and the small oblong slit right above the



P.O. Box 558 | 3325 Grassy Hill Road | Rocky Mount, VA | 24151 www.uttermost.com