



UTTERMOST

Item#23277

Parts list

| | |
|-----------------|------|
| Top Assembly | 1 pc |
| Leg base | 2 pc |
| cross metal bar | 1 pc |

Assembly Instruction

Hardware list


| | |
|--------------|-------|
| Screw | 4 pcs |
| Nut | 4 pcs |
| Spanner | 1 pc |
| Allen wrench | 1 pc |



(A)



(B)



(C)



(D)

1. Take all parts out of the carton carefully and place on a clean flat surface.

2. Screw the legs into top as illustrated A and B with screws .

3. Screw the cross metal bar as illustrated C with Nuts .

4. Use spanner and allen wrench to secure tightly. Then turn right side up.

5. Assembly is complete.