



UTTERMOST


Assembly Instruction

Item :24338


Parts/Hardware list

A	Top Frame	1 PC	E	Short Leg Tube	4PCS
B	Thread Rod	4PCS	F	Bottom Foot	4 PCS
C	Long Leg Tube	4PCS	G	Felt Pad	4PCS
D	Stretcher	1 PC	H	Glass Top	1PC

1. Take the parts carefully out of the carton, and place them on a flat and soft surface, making sure that the parts will not be damaged.
2. Place Top Frame (A) upside down on a flat & soft surface.
3. Scew 4 Thread Rod (B) on Top Frame (A) individually.
4. Put the Long Leg Tube (C) on the Thread Rod(B),
let Thread rods (B) pass through 4 Long Leg Tube (C).
5. Put the Stretcher(D) on the Thread Rod(B),
Let the Thread Rod(B) pass through the 4 holes of the Stretcher(D).
6. Put the Short Leg Tube (E) on the Thread Rod(B),
let the Thread Rod(B) pass through the Short Leg Tube (E).



(1)



(2)

7. Screw 4 Bottom Foot (F) on the end of the Thread Rod(B) till all parts are tight.
8. Stick the Felt pads (G) on the bottom of 4 Bottom Feet (F).
9. Turn over table, and place the Class Top (H) on the Top Frame (A)
as show in above picture (2).
- 10 . To Clean, wipe with dry cloth.