




UTTERMOST
Assembly Instruction
 STYLE: 24617

Parts list

A	METAL LEG	2PCS
B	GLASS TOP	3PCS

Hardware list

GASKET	12PCS
SCREW	12PCS
WRENCH	1PC



1. Take metal leg parts carefully out of the carton and place it on a flat surface, make sure that the parts will not be damaged.

2 . Use wrench lock screw glass top into metal leg of each layer

3.Put the table upside down and the assembly is complete.

To Clean, wipe with soft dry cloth.