



UTTERMOST

Item#24836

Parts list

Metal Bar	4 pcs
Wood leg	4 pcs
Table top	1 pc

Assembly Instruction

Hardware list

Bolt	12 pcs
Nut	4 pcs
Spanner	1 pc



A



B



1. Take all parts out of the carton carefully and place on a clean flat surface.

2. Screw the wood legs into top as illustrated A with bolts and nuts .

3. Screw the metal bar as illustrated B with bolts .

4. Use spanner to secure tightly. Then set table upright

5. Assembly is complete.