



UTTERMOST

Item#24876

Parts list

leg with wheels	2 pcs
tray	3 pcs

Assembly Instruction

Hardware list

nut	12 pcs
Spanner	1 pc


Ⓐ



1. Take all parts out of the carton carefully and place on a clean flat surface.

2. Lay two legs with wheels down on the floor as illustrate A

Ⓑ



3. Screw trays on the legs with nuts as illustrate B according to the labels, A for A, B for B , C for C.

Ⓒ



4. Use spanner to secure tightly.

Ⓓ



5. Then turn right side up. Assembly is complete.