




THE UTTERMOST CO.

ASSEMBLY INSTRUCTIONS FOR
ITEM # 19150



Unscrew the pre-fitted pillar cup. Insert glass, and re-tighten pillar cup.
Warning: To avoid cracking of glass do not over-tighten screw cap