



UTTERMOST

21246

FIXTURE ASSEMBLY

1. Thread wires through the parts in order as shown.
2. Place cap and small ring over nipple of body and secure with center tube.
3. Place shade, big ring, crystal and other big ring over nipple of center tube and secure with loop.

