



UTTERMOST

Item#23091


Parts list

Top Assembly	1 pc
Leg base	1 pcs
Metal bars	2 pcs

Assembly Instruction

Hardware list

Nuts	10 pcs
Flat Washer	10 pcs
Allen screw	4 pcs
Spanner	1 pc
Wrench	1 pc



(A)

(B)



(C)

(D)

1. Take all parts out of the carton carefully and place on a clean flat surface.
2. Open the folded leg, then screw into stool top as illustrated photo in A and B with nuts and flat washer.
3. Screw two metal bars into leg base in separate ends as illustrated in photo C with allen screws.
4. Use spanner and wrench to secure tightly. Finally put upside down as shown in photo D.