




UTTERMOST

Assembly Instruction

STYLE: 24277

Parts / Hardware list					
A	Threaded Rod with feet	4 PCS	G	Top Glass Shelf	1pc
B	"X" Stretcher	1 PC	H	Ribbed Tube (Shorter)	4pcs
C	Glass Shelf	3 PCS	I	Connector	4pcs
D	Ribbed Tube (Longer)	12 PCS	J	Bottom Finial	1pc
E	Threaded Finial	4 PCS	K	Glass with Green dot	3pcs
F	Felt pad	4 PCS	L	Gass with with Red dot	1pc



1. Take the parts carefully out of the carton, and place them on a flat and soft surface, making sure that the parts will not be damaged

2. Take off all parts from Threaded Rod (A) except 4 feet.

3. Insert 4 Threaded Rods (A) through 4 corners of "X" Stretcher (B).

4. Slide-in the 4 Ribbed Tubes (Longer) (D) into 4 Threaded Rods (A). Then place Glass Shelf (C) on top.

5. Repeat Step #4 four two times.


6. Slide-in the 4 Ribbed Tubes (Shorter)(H), 4 connector (I) into 4 Threaded Rods (A), Then place Glass Shelf (G) on top.

7. Screw 4pcs Threaded Finials (E) on the top of Threaded Rods (A). Then tighten all parts together.

8. Screw Bottom Finial (J) on the center of "X" Stretcher (B).

9. Stick the Felt pad(F) on the bottom of 4 feet.

10. Place Glass (K) with green dot on 3 lower Glass shelf (C), and Glass (L)with red dot on Top Glass shelf (G).



To Clean, wipe with soft dry cloth.