MANUFACTURERS OF WALL DECOR, LIGHTING,

DECORATIVE ACCESSORIES AND ACCENT FURNITURE

UTTERMOST

Assembly Instruction STYLE: 24447

Parts list

Α	METAL SHELF	1PC
В	SHELF BRACKET	2PC
F	GLASS TOP OF SHELF	4PCS


Hardware list

SMALL SUCTION CUPS	16PCS
WRENCH	1PCS
SCREW	14PCS



1. Take metal shelf part (A)carefully out of,

the carton and place it on a flat surface, make sure that the parts will not be damaged.



2. Screw the shelf bracket in the bottom part.


С



3. Use Wrench screw into the hole on the back.



4. Put the small suction cups into the hole.





5. Put the glass top on each layer.

6. Key holes and anchor and screw are for tipping protection. Screw in keyhole should not be completely engaged in top of slot to support weight.

just used to lock the item to the wall and prevent tipping.

PO BOX 558/3325 GRASSY HILL RD. ROCKY MOUNT, VIRGINIA 24151 www.uttermost.com