



UTTERMOST

# Assembly Instructions

## STYLE: 24851

### Parts list

A	METAL TABLE TOP	1 PC
B	GLASS TOP	1 PC
C	METAL LGE	2 PCS

### Hardware list

SCREW	7 PCS
WRENCH	1 PC

1. Take the parts carefully out of the carton, and place them on a flat surface, make sure that the parts will not be damaged.


2. Place the lower part of table leg on a flat surface




3. Place the upper part of table leg onto the lower part. Use Allen wrench and screw two parts of table legs together.



4. Use Allen wrench and screw table top to base



4. Place glass on top.



5. To clean, wipe with soft dry cloth. Finished.

