
UTTERMOST ASSEMBLY INSTRUCTIONS

Assembly Instruction STYLE: 25229

Parts list				Hardware list	
Α	GLASS TOP	1PC		SCREW (size: M6X15MM)	16PCS
В	GLASS SHELF	1PC		WRENCH	1PC
С	METAL BAR CART TOP FRAME	1PC			
D	METAL BAR CART SHELF FRAME	1PC			
Ε	METAL BAR CART LEG	4PCS			



1. Take the parts carefully out of the carton, and place

them on a flat surface. Make sure that the parts will not be damaged.

- 2. Use wrench to screw bar cart's first leg to the top frame and shelf frame.
- 3. Use wrench to screw bar cart's second leg to the top frame and shelf frame.
- 4. Use wrench to screw bar cart's third leg to the top frame and shelf frame.
- 5. Use wrench to screw bar cart's fourth leg to the top frame and shelf frame.
- 6. Place glass on top and shelf. To clean, wipe with soft dry cloth. Assembly is complete

P.O. Box 558 | 3325 Grassy Hill Road | Rocky Mount, VA | 24151 www.uttermost.com