

UTTERMOST

ASSEMBLY INSTRUCTIONS


ITEM.: 50170

Page 1 of 1

PART LIST		
NO.	DESCRIPTION	QTY
1	Top	1 PC
2	Base	1 PC

HARDWARE			
A	Flat washer		4 pcs
B	Lock washer		4 pcs
C	Bolt		4 pcs
D	Allen wrench		1 pc

Step 1 Lay the Table Top (1) upside down on a soft, flat surface.
Assemble the Base (2) as shown below using hardware (A, B, C).



1

Step 2 Use a Team Lift to set the table upright. Assembly is complete.

Complete