




UTTERMOST

ASSEMBLY INTRUCTION FOR ITEM #25411



① Top - 1 pc



② Leg - 4 pcs



Ⓐ Flat Head machine
Screw $\text{Ø}1/4" \times 1" = 8 \text{ pcs}$



Ⓑ Lock Washer $\text{Ø}1/4" = 8 \text{ pcs}$



Ⓒ Flat Washer $\text{Ø}1/4" = 8 \text{ pcs}$



Ⓓ Allen Wrench 4mm
= 1 pc

